

Glenaboy Stream nr Lype

W 983888

Cyril received a complaint re soft
lean timber in position. action is to
Glenaboy & then into the Bannister
SAC @ Tallow.

I called at site @ 1200 - 1300

No machines or SAC, no one present

Can see ahead in stream

Good plan is in web of trees

been badly churned up, kind of
present in Machine tracks. Lots
as though timber operations
were in progress. Lots of brush
in Machine tracks, definitely machine

to central site? No run off

New Harbour the stream. It
point, a temporary crossing has
been put in over the stream,
consists of a mass of posts

Timber also gone on the far
west side of the stream

From behind 3 rows of trees
of the vegetation
was each

10/1/21
3 ft. plants of some
of water

1540 — 1705
Close to the ground 2 1/2 days

1030 1 Row of trees →
was each 4 rows 4 rows

25/11/21

Lough Beg

MS 5 (1st, 2nd)

MA 3

GA 4, 3

SD 10, 2

AG 3, 3

BH 22

CM 1