

Ken Bucke images 8 Dec.



Stream location
indicated by arrows
and silt being held
back by a brush dam
at the time of inspection





Forest road c. 150m upslope of stream

Rutted forwarding route



Forest road



Sediment evident on streambed



Forwarding route



Forwarding route



Silt retained in the forest



Evidence of silt mobilised in the forest

Image provided by IFI at the time of the incident (may have been taken by a member of the public)

