























































J

040A

From: [Jim Fanning](#)
To: [REDACTED]
Cc: [REDACTED]@awnconsulting.com; [REDACTED] <[REDACTED]@kilsaran.ie>
[REDACTED]@kilsaran.ie; Darren Arkins
Subject: RE: Sea Green
Date: 21 June 2016 09:51:00

Thanks Karl,
Methodology noted as similar to Sea Road. If/when schedule and appointments finalised, please let me know.
Jim Fanning

James Fanning | Inspector, Occupational Hygiene
Health and Safety Authority,
The Metropolitan Building, James Joyce Street, Dublin 1
D01 K0Y8 .

Tel: 01-6147056
Email: jim_fanning@hsa.ie
Web: www.hsa.ie

Healthy, Safe and Productive Lives

From: [REDACTED] [mailto:[REDACTED]@okellybros.ie]
Sent: 20 June 2016 19:58
To: Jim Fanning
Cc: [REDACTED]@awnconsulting.com; [REDACTED] <[REDACTED]@kilsaran.ie>
([REDACTED]@kilsaran.ie)
Subject: Sea Green

Good evening Jim,

Please see attached the method statement and risk assessment for the works at Sea Green Greystones Co. Wicklow.


If you have any queries please do not hesitate to contact us.

Regards

[REDACTED]
Mobile + 353 87 [REDACTED]
[REDACTED]@okellybros.ie

O'Kelly Bros Ce. Ltd.
Demolition and Environmental Contractors.
Jutland Hall.
Dock Road.
Limerick.

P: +35361 [REDACTED]
F: +35361 40 41 61

 **Before printing, think about the environment**

From: [REDACTED]
To: [Jim Fanning](#); [REDACTED]
Cc: [Darren Arkins](#)
Subject: RE: 3220 Kilsaran Filter Details - Sea Road site
Date: 20 June 2016 18:13:06

Hi Jim,

Depending on when we commence this project - Reassurance monitoring will be either [REDACTED] or G&L Consultancy Ltd. We will advise as soon as we have a start date.

Kind Regards

[REDACTED]
AWN Consulting
The Tecpro Building
IDA Business and Technology Park
Clonshaugh
Dublin 17

[Click for map](#)

e: [REDACTED]@awnconsulting.com

w: www.awnconsulting.com

[View my LinkedIn profile](#)

Please consider the environment before printing this email.

"This communication contains information which is confidential, and is for the exclusive use of the addressee(s). If you are not a named addressee please contact the sender immediately, and delete the communication from your system. Any views or opinions presented are solely those of the author and do not necessarily represent AWN Consulting Limited unless specifically stated."

AWN Consulting Limited registered in Ireland No. 319812

-----Original Message-----

From: Jim Fanning [mailto:jim_fanning@hsa.ie]

Sent: 20 June 2016 17:10

To: [REDACTED] <[REDACTED]@okellybros.ie>

Cc: [REDACTED] <[REDACTED]@awnconsulting.com>; Darren Arkins <darren_arkins@hsa.ie>

Subject: RE: 3220 Kilsaran Filter Details

Thanks [REDACTED].

I presume you are planning to start at the Sea Road, Kilcoole site. Please confirm appointed analyst and PSDP at this site.

Kind regards

Jim Fanning

-----Original Message-----

From: [REDACTED] [[mailto:\[REDACTED\]@okellybros.ie](mailto:[REDACTED]@okellybros.ie)]

Sent: 20 June 2016 15:59

To: Jim Fanning

Cc: Kilsaran AWN [REDACTED]

Subject: 3220 Kilsaran Filter Details

Jim

Please find attached the specification for the air filters as discussed.

If you have any queries please do not hesitate to give me a call.

Regards



O'Kelly Bros CE LTD
The Square
Ballingarry
Co Limerick

This email and any files transmitted with it are confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error please notify the system manager.

The Health and Safety Authority, its servants or agents, accept no liability for any errors or omissions in the information provided in this correspondence or for any loss or damage occasioned to any person as a result of using the information provided.

This footnote also confirms that this email message has been swept for the presence of computer viruses.



This communication contains information which is confidential, and is for the exclusive use of the addressee(s). If you are not a named addressee please contact the sender immediately, and delete the communication from your system. Any views or opinions presented are solely those of the author and do not necessarily represent Awn Consulting Limited unless specifically stated.

This footer also confirms that this e-mail message has been scanned for the presence of computer viruses. Scanning of this message and addition of this footer is performed by Microsoft Office 365 email gateway, IT service provider company Ergo Group.

Awn Consulting Limited registered in Ireland No. 319812



This communication contains information which is confidential, and is for the exclusive use of the addressee(s). If you are not a named addressee please contact the sender immediately, and delete the communication from your system. Any views or opinions presented are solely those of the author and do not necessarily represent Awn Consulting Limited unless specifically stated.

This footer also confirms that this e-mail message has been scanned for the presence of computer viruses. Scanning of this message and addition of this footer is performed by Microsoft Office 365 email gateway, IT service provider company Ergo Group.

From: [REDACTED]
To: [Jim Fanning](#)
Cc: [Kilsaran AWN](#) [REDACTED]
Subject: 3220 Kilsaran Filter Details
Date: 20 June 2016 15:58:57
Attachments: [Skannad med en Xerox flerfunktionsenhet.pdf](#)
[ATT00001.txt](#)
[416-126 filter spec.pdf](#)
[ATT00002.txt](#)

Jim

Please find attached the specification for the air filters as discussed.

If you have any queries please do not hesitate to give me a call.

Regards

[REDACTED]

O'Kelly Bros CE LTD
The Square
Ballinarry
Co Limerick

SUODATINTEHDAS

AIRFIL OY

Vakkistentie 22
FIN-37830 VIIALA
FINLAND



20.7.2007

AIR FILTER
TECHNICAL SPECIFICATION
AFA-6023/D ABS=416-123

FILTER MEDIA: F5 (EN779) POLYESTER +GLASS FIBRE+F5 (EN 779) POLYESTER

FILTRATION RATING FOR AIR 0,3 µm 99,995% (DOP).

Fractional collection efficiency for MPPS EN 1822 H10

Mass retention efficiency according to BIA (DIN 60335-2-69 annex AA) BIA H

AREA 9,4 M²

OUTER Ø 307 MM

INNER Ø 200 MM

HEIGHT H=685+GASKET 13=698 MM

OUTER + INNER PERFORATED SUPPORT TUBE

OUTER SUPPORT GLUE STRIPES (Hot melt glue)

FLOW Q=170 L/S =612 M³/H AT DELTA P=200 Pa

TEMPERATURE +100°C

AIRFIL OY



PUH: 03 - 57 44 500
TEL: +358 3 5744 500
E-mail: sales@airfil.fi

FAX: 03 - 57 44 530
FAX: +358 3 5744 530
Homepage <http://www.airfil.fi>

Ly-tunnus: 0399295-7

VAT: FI03992957

ALV rek.

Kaupparek.nro 288.093

Trade Reg. No. 288.093

Kotipaikka: Viiala



TECHNICAL SPECIFICATION

AIR FILTER


AFA-598/D/ABS/H10

DISAB 416-126

DATED 23.03.2009/RS

Measures/Mitat:

H1= 360 mm
 H2= 368 mm
 OD1= 307 mm
 OD2= 307 mm
 ID1= 200 mm
 ID2= 11 mm



Construction/Rakenne:

END CAPS: Metal
 GASKETS: Rupper h=8 mm
 OUTER PERFORATED TUPE: Yes
 INNER PERFORATED TUPE: Yes
 Temperature +100°C

Filtration:

Filter media: EU5 Polyester+Glass Fibre EU10 + EU5 Polyester (EN779)
 Filter area: 4,9 m²
 Flow Q 90 lit/sek=324 m³/h
 at Δ. P=200 Pa

Fractional collection efficiency for MPPS EN 1822 H10
 Mass retention efficiency according to BIA (DIN 60335-2-69 annex AA) BIA H

From: [Jim Fanning](#)
To: [Darren Arkins](#)
Subject: FW: Results for Kilsaran Quarry Ballinclare
Date: 17 June 2016 17:07:00

Darren

Just for record, to provide context for "Crusher Dust Samples" and for results just received. These 6 samples, (inadvertently named SS1,...-SS6, same as some earlier samples) are understood to have been taken by AWN/Hegarty personnel from the very fine dust that we saw collected directly under the primary crusher.

Jim

From: [redacted] [mailto:[redacted]@awnconsulting.com]
Sent: 15 June 2016 10:07
To: Jim Fanning
Cc: [redacted]
Subject: RE: Results for Kilsaran Quarry Ballinclare

Good morning Jim

The results from the ChemTest report, samples SS1 – SS6, do not correspond to the sampling sites from the figure as the sample numbers were just re-used.

The figure shows the main sampling done at the site whilst the ChemTest report shows the results from the samples taken around the face of the excavation where the crushers are located.

I hope this clarifies things.

Kind regards,

[redacted]

AWN Consulting
The Tecpro Building
IDA Business and Technology Park
Clonshaugh
Dublin 17

e: [redacted]@awnconsulting.com
w: www.awnconsulting.com

[Click for map](#)

Please consider the environment before printing this email.

"This communication contains information which is confidential, and is for the exclusive use of the addressee(s). If you are not a named addressee please contact the sender immediately, and delete the communication from your system. Any views or opinions presented are solely those of the author and do not necessarily represent AWN Consulting Limited unless specifically stated."

AWN Consulting Limited registered in Ireland No. 319812

From: Jim Fanning [mailto:jim_fanning@hsa.ie]
Sent: 14 June 2016 17:37
To: [redacted] <[redacted]@awnconsulting.com>
Subject: RE: Results for Kilsaran Quarry Ballinclare

[redacted]

I presume then that you mean samples SS1,...SS6, as per your 1st attachment. Results here do not appear to correspond to SS1, ...SS6 as shown in separate map/legend (ie your final attachment).

Jim

From: [redacted] [mailto:[redacted]@awnconsulting.com]
Sent: 14 June 2016 17:28
To: Jim Fanning
Cc: [redacted]
Subject: RE: Results for Kilsaran Quarry Ballinclare

Hi Jim

They should be the ones in the separate ChemTest report.

Regards,

[redacted]

AWN Consulting
The Tecpro Building
IDA Business and Technology Park
Clonshaugh

e: [redacted]@awnconsulting.com
w: www.awnconsulting.com

Dublin 17

[Click for map](#)

Please consider the environment before printing this email.

"This communication contains information which is confidential, and is for the exclusive use of the addressee(s). If you are not a named addressee please contact the sender immediately, and delete the communication from your system. Any views or opinions presented are solely those of the author and do not necessarily represent AWN Consulting Limited unless specifically stated."

AWN Consulting Limited registered in Ireland No. 319812

From: Jim Fanning [mailto:jim_fanning@hsa.ie]

Sent: 14 June 2016 17:16

To: [REDACTED] <[REDACTED]@awnconsulting.com>

Subject: RE: Results for Kilsaran Quarry Ballinclare

Hi [REDACTED]

I have been looking at the documents attached to your mail below. Could you clarify for me which docs/results refer to the dust samples from beneath the crushers.

Thanks

Jim

From: [REDACTED] [mailto:[\[REDACTED\]@awnconsulting.com](mailto:[REDACTED]@awnconsulting.com)]

Sent: 13 June 2016 17:30

To: Jim Fanning

Cc: [REDACTED]

Subject: Results for Kilsaran Quarry Ballinclare

Good afternoon Jim

Please find attached the soil sampling map for the quarry as well as the results from the dust samples taken beneath the crushers.

I have also attached details of the air sampling data analysed by IOM which are summarised in the table below (please note some results from the PDFs do not relate to the quarry site). [REDACTED] will send over the additional results from [REDACTED] later this evening.

IOM Air Asbestos Analysis Summary

Site Name	Sample ID	Sampling Location	IOM Analysis Contract No	Batch ID
Kilsaran Quarry Ballinclare	B1	Office	48698	B
	B2	next to green cabin, sw of site		
	B3	Quarry Floor NW of site		
	B4	High up NW of Site		
	I1	Opposite Ballinclare house	48769	I
	I2	330m SE of site entrance on road		
	I3	500 m NE of site entrance, receptor house		
	I4	NW of site boundary on road		
	J1	Quarry Entrance	48802	J
	J2	Coakley House, Back Wall of House		
	J3	Gate to Wicklow CoCo Depot		
	K7	Quarry Gate	48818-1	K
	K8	Opposite Ballinclare House Entrance		
	M6	Quarry Entrance	48830	M
M7	Gate to Wicklow CoCo Depot			

Kind regards,

[REDACTED]

AWN Consulting
The Tecpro Building
IDA Business and Technology Park
Clonsillaugh
Dublin 17

e: [REDACTED]@awnconsulting.com

w: www.awnconsulting.com

[Click for map](#)

Please consider the environment before printing this email.

"This communication contains information which is confidential, and is for the exclusive use of the addressee(s). If you are not a named addressee please contact the sender immediately, and delete the communication from your system. Any views or opinions presented are solely those of the author and do not necessarily represent AWN Consulting Limited unless specifically stated."

AWN Consulting Limited registered in Ireland No. 319812

This communication contains information which is confidential, and is for the exclusive use of the addressee(s). If you are not a named addressee please contact the sender immediately, and delete the communication from your system. Any views or opinions presented are solely those of the author and do not necessarily represent AWN Consulting Limited unless specifically stated.

From: [Jim Fanning](#)
To: [Darren Arkins](#)
Subject: FW: Kilsaran Quarry Dust Further Analysis
Date: 17 June 2016 17:02:00
Attachments: [Standard Report_16-12750-20160617_150113.pdf](#)

Darren

See additional test results for "Crusher Dust Samples", 2 samples tested for free fibre analysis as per draft "Blue Book".

Jim

From: [redacted] [mailto:[redacted]@awnconsulting.com]
Sent: 17 June 2016 16:36
To: Jim Fanning
Cc: [redacted]
Subject: Kilsaran Quarry Dust Further Analysis

Hi Jim,

Apologies for the delay Jim, please see attached results for further analysis that was done for quarry dust samples, namely samples **SS4** and **SS5**. Relevant results are those labelled under '*Asbestos by Fibre Counting*'.

Kind Regards,

[redacted]

AWN Consulting
The Tecpro Building
IDA Business and Technology Park
Clonshaugh
Dublin 17

e: [redacted]@awnconsulting.com
m: + [redacted]
w: www.awnconsulting.com

[Click for map](#)

Please consider the environment before printing this email.

This communication contains information which is confidential, and is for the exclusive use of the addressee(s). If you are not a named addressee please contact the sender immediately, and delete the communication from your system. Any views or opinions presented are solely those of the author and do not necessarily represent AWN Consulting Limited unless specifically stated.

This footer also confirms that this e-mail message has been scanned for the presence of computer viruses. Scanning of this message and addition of this footer is performed by [Microsoft Office 365](#) email gateway, IT service provider company [Ergo Group](#).



Amended Report

Report No.: 16-12750-2

Initial Date of Issue: 01-Jun-2016 **Date of Re-Issue:** 17-Jun-2016

Client: AWN Consulting

Client Address: The Tecpro Building
Clonshaugh Business and Techno
Dublin 17
Ireland
Ireland

Contact(s): [REDACTED]
[REDACTED]

Project: 16-9020 Ballinclare, Quarry


Quotation No.: Q16-06538 **Date Received:** 31-May-2016

Order No.: **Date Instructed:** 31-May-2016

No. of Samples: 6

Turnaround (Wkdays): 14 **Results Due:** 17-Jun-2016

Date Approved: 17-Jun-2016

Approved By:


Details: [REDACTED]

Results - Soil

Client: AWN Consulting		Chemtest Job No.:				16-12750	16-12750	16-12750	16-12750	16-12750	16-12750
Quotation No.: Q16-06538		Chemtest Sample ID.:				301703	301704	301705	301706	301707	301708
		Client Sample ID.:				SS 1	SS 2	SS 3	SS 4	SS 5	SS 6
		Sample Type:				SOIL	SOIL	SOIL	SOIL	SOIL	SOIL
		Date Sampled:				30-May-2016	30-May-2016	30-May-2016	30-May-2016	30-May-2016	30-May-2016
Determinand	Accred.	SOP	Units	LOD							
ACM Type	U	2192		N/A	Fibres/Clumps	Fibres/Clumps	Fibres/Clumps	Fibres/Clumps	Fibres/Clumps	Fibres/Clumps	Fibres/Clumps
Asbestos Identification	U	2192	%	0.001	Actinolite	Actinolite	Actinolite	Actinolite	Actinolite	Actinolite	Actinolite
Asbestos by Gravimetry	U	2192	%	0.001	0.001	0.100	0.001	0.16	0.048	0.099	
Asbestos By Fibre Counting	U	2192	%	0.001				0.014	0.003		
Total Asbestos	N	2192	%	0.001	0.001	0.100	0.001	0.16	0.048	0.099	

Report Information

Key

- U UKAS accredited
- M MCERTS and UKAS accredited
- N Unaccredited
- S This analysis has been subcontracted to a UKAS accredited laboratory that is accredited for this analysis
- SN This analysis has been subcontracted to a UKAS accredited laboratory that is not accredited for this analysis
- T This analysis has been subcontracted to an unaccredited laboratory
- I/S Insufficient Sample
- U/S Unsuitable Sample
- N/E not evaluated
- < "less than"
- > "greater than"

Comments or interpretations are beyond the scope of UKAS accreditation

The results relate only to the items tested

Uncertainty of measurement for the determinands tested are available upon request

None of the results in this report have been recovery corrected

All results are expressed on a dry weight basis

The following tests were analysed on samples as received and the results subsequently corrected to a dry weight basis TPH, BTEX, VOCs, SVOCs, PCBs, Phenols

For all other tests the samples were dried at < 37°C prior to analysis

All Asbestos testing is performed at our Coventry laboratory

Issue numbers are sequential starting with 1 all subsequent reports are incremented by 1

Sample Deviation Codes

- A - Date of sampling not supplied
- B - Sample age exceeds stability time (sampling to extraction)
- C - Sample not received in appropriate containers
- D - Broken Container

Sample Retention and Disposal

All soil samples will be retained for a period of 45 days from the date of receipt

All water samples will be retained for 14 days from the date of receipt

Charges may apply to extended sample storage

If you require extended retention of samples, please email your requirements to:

customerservices@chemtest.co.uk

From: [Jim Fanning](#)
To: [REDACTED] [awnconsulting.com](mailto:[REDACTED]@awnconsulting.com)
Subject: RE: Ballinclare
Date: 17 June 2016 14:34:00

Hi [REDACTED]

I would like to speak to someone in AWN this pm about a sampling issue that has arisen in relation to the Seagreen site, would appreciate a return call.

Jim

From: Jim Fanning
Sent: 16 June 2016 16:44
To: [REDACTED]
Subject: RE: Ballinclare

Hi [REDACTED]

I wanted to discuss decon works in quarry (as per Gravity RAMS)

Jim

From: [REDACTED] [[mailto:\[REDACTED\]@awnconsulting.com](mailto:[REDACTED]@awnconsulting.com)]
Sent: 16 June 2016 16:36
To: Jim Fanning
Subject: RE: Ballinclare

Hi Jim

I've sent her a message. I know she is offsite in meetings all day today. What is your inquiry regarding?

Regards,

[REDACTED]

AWN Consulting
The Tecpro Building
IDA Business and Technology Park
Clonshaugh
Dublin 17

e: [REDACTED] [awnconsulting.com](mailto:[REDACTED]@awnconsulting.com)

w: www.awnconsulting.com

[Click for map](#)

Please consider the environment before printing this email.

"This communication contains information which is confidential, and is for the exclusive use of the addressee(s). If you are not a named addressee please contact the sender immediately, and delete the communication from your system. Any views or opinions presented are solely those of the author and do not necessarily represent AWN Consulting Limited unless specifically stated."

AWN Consulting Limited registered in Ireland No. 319812

From: Jim Fanning [mailto:jim_fanning@hsa.ie]
Sent: 16 June 2016 16:31

To: [REDACTED] <[REDACTED]@awnconsulting.com>

Subject: Ballinclare

Hi [REDACTED]

I'm trying to contact [REDACTED] this pm. Would it be possible to pass her a message asking her to give me a call.

Thanks

Jim Fanning

James Fanning | Inspector, Occupational Hygiene
Health and Safety Authority
The Metropolitan Building, James Joyce Street, Dublin 1
Tel: 01 6147056 | Fax: 01 6147020
Email: jim_fanning@hsa.ie | Web: www.hsa.ie

A Culture of Workplace Safety and Health for All

This email and any files transmitted with it are confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error please notify the system manager.

The Health and Safety Authority, its servants or agents, accept no liability for any errors or omissions in the information provided in this correspondence or for any loss or damage occasioned to any person as a result of using the information provided.

This footnote also confirms that this email message has been swept for the presence of computer viruses.

This communication contains information which is confidential, and is for the exclusive use of the addressee(s). If you are not a named addressee please contact the sender immediately, and delete the communication from your system. Any views or opinions presented are solely those of the author and do not necessarily represent Awn Consulting Limited unless specifically stated.

This footer also confirms that this e-mail message has been scanned for the presence of computer viruses. Scanning of this message and addition of this footer is performed by [Microsoft Office 365](#) email gateway, IT service provider company [Ergo Group](#).

Awn Consulting Limited registered in Ireland No. 319812

From: [REDACTED]
To: [Jim Fanning](mailto:Jim.Fanning@awnconsulting.com)
Cc: [REDACTED] awnconsulting.com; [REDACTED]
Subject: Sea Road Additional items
Date: 17 June 2016 11:56:34
Attachments: [3220 RAMS 002 Sequencing of works at Sea Road Rev 03 160615.pdf](#)
[3223 RAMS 001 For tipping of ACM"s at Ballinclare Quarry 160615 \(2\).pdf](#)

Jim

Please see attached as discussed. I will forward the vac unit and filter specifications later. Please give me a call to discuss any queries.

If you have any queries please do not hesitate to contact us.

Regards

[REDACTED]
Mobile + 353 87 [REDACTED]
[REDACTED] okellybros.ie

O'Kelly Bros Ce. Ltd.
Demolition and Environmental Contractors.
Jutland Hall.
Dock Road.
Limerick.

P: +35361 [REDACTED]
F: +35361 40 41 61

 **Before printing, think about the environment**



2015/2016

This email and all attachments are confidential and intended solely for the use of the person or company to whom they are addressed. If you have received this email in error please notify info@okellybros.ie

METHOD STATEMENT, SAFE SYSTEM OF WORK PLAN AND RISK ASSESSMENT



O'KELLYBROS
DEMOLITION & ENVIRONMENTAL
CONTRACTORS

Description: Detailed Sequencing of the execution at Sea Road, Kilcoole, Co. Wicklow.

Job No: 3220

Date: 15-06-2016

Prepared by: [REDACTED]

Doc no. 3220 RAMS 001

REV
001

Page 1 of 15

Co-ordination and Information

Client Kilsaran Concrete Products:
Main Contractor: O'Kelly Bros
PSDP: O'Kelly Bros
PSCS: O'Kelly Bros
Air Monitoring / Analytical : AWN Consulting / [REDACTED]

Contact: [REDACTED]

Contact: O'Kelly Bros [REDACTED]

Description of and Sequence of Work

Location: Sea Road, Kilcoole, Co. Wicklow.

Commencement Date: 16-06-16

EST Duration: 2 -3 weeks ()

Description of Work:

Remediation of ACM's in soil and stones.

Supervision

Supervisor / Foreman: [REDACTED]

Contact No: 087- [REDACTED]

Supervisor checks: Compliance with site procedures.

<input checked="" type="checkbox"/> Fencing intact	<input checked="" type="checkbox"/> Works as per RAMS	<input checked="" type="checkbox"/> Noise/Dust Nuisance	<input type="checkbox"/> Personal Flotation Devices
<input checked="" type="checkbox"/> Equipment in GWO	<input type="checkbox"/> Fire Hydrant located & in-service	<input checked="" type="checkbox"/> Isolations inspected and shown to Ex Op	<input checked="" type="checkbox"/> T Mgt working ok
<input checked="" type="checkbox"/> Weather conditions	<input checked="" type="checkbox"/> Daily Inspection log	<input checked="" type="checkbox"/> Decontamination Equipment	<input checked="" type="checkbox"/> Specialised Dust Suppression Equipment

Sequence of Task –Pre-planning

Sequence of Task –Pre-planning		Risk Assessment/ Control
No:	<p>OVERVIEW <i>Independent Air Analyst appointed by Kilsaran to carry out Inspections. Kilsaran Concrete Products – The Controlling Body O'Kelly Bros to carry out all ACM handling in relation to removal / remediation to agreed area. (OKB)</i></p> <p>Operational Sequence & Additional Control Measures</p>	Ref No:
01	<p>Fence the site and establish welfare & decontamination equipment.</p> <p>Setup Isolations / route demarcation around the work area and the connecting routes. Setup localised decontamination area at the work face. Self-contained waste stream decontamination wash room unit available for operatives to use.</p> <p>Reporting; Written Confirmation of formal notification to HSA for ACM will be available for inspection.</p>	
02	AWN with O Kelly Bros to walk and confirm the area of works.	
03	Air monitoring points identified and air monitoring established on site. Inspection, Monitoring & Sampling by the Air Analyst will be in place prior to any works commencing so that there is a background check to confirm the readings of previous monitoring data.	

METHOD STATEMENT, SAFE SYSTEM OF WORK PLAN AND RISK ASSESSMENT

Description: Detailed Sequencing of the execution at Sea Road,
Kilcoole, Co. Wicklow.

Job No: 3220

Date: 15-06-2016

Prepared by: [REDACTED]

Doc no. 3220 RAMS 001

REV
001

Page 3 of 15



O'KELLYBROS
DEMOLITION & ENVIRONMENTAL
CONTRACTORS

A. Sea Road General Arrangement / Location of Works.



Access Route in Green
Work areas in Red Line
Location of DCU in Blue

DCU location will follow the progression of the work and will be relocated as necessary.

See work zone layout as per sketch below.